General Environmental Incident Summary

Incident: 2167 Date/Time Notice: 1/7/2014 1627 DEM Incident No:

Responsible Party: Marathon Oil Company

Date Incident: 1/6/2014 Time Incident: 0600 Duration:

County: Dunn Twp: 146 Rng: 95 Sec: 24 Qtr: SW SE

Lat: 47.44529 Long: -102.73080 Method: Navigation quality GPS

Location Description: * From Dickinson,; travel ~ 28.6 miles N on Hwy 22 thru Killdeer, then

continue 0.7 miles N.

* Turn right onto gravel at Medicine Hole Golf Course sign, travel 1 mile to 1st

St (Y).

* Turn left at "Y" heading due north onto 104th Ave and travel 3.1 miles to

2nd St NW,

* Turn right (east), travel 1.3 miles to location on left (north).

Submitted By: Luis Londono Affiliation: HES Professional

Address: 3172 Highway 22 North

City: Dickinson State: ND Zip: 58601

Received By:
Contact Person:

3172 Highway 22 North

Dickinson, ND

Distance Nearest Occupied Building: 1.5 Miles

Type of Incident: Camlock fitting leak

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 5.00 barrels Ag Related: No EPA Extremely Hazardous Substance: No Reported to NRC: No

Cause of Incident:

While making a fluid transfer from the tank farm, a brass camlock fitting failed, releasing 5 bbls of diesel into containment (double lined secondary containment). All fluid was contained and none contacted unprotected ground.

Risk Evaluation:

No immediate risks identified.

of Fatalities: 0 # of Injuries: 0 Affected Medium: 09 - other

Potential Environmental Impacts:

No potential environmental impacts to surface water, ground water, or soils. The release was contained to the double-lined secondary containment that holds the tank farm.

Action Taken or Planned:

Diesel fuel around the fitting that leaked was removed using a vacuum truck. No fluid contacted unprotected ground.

Wastes Disposal Location: Recovered diesel fuel will be taken to an approved disposal.

Agencies Involved:

Updates

Date: 1/8/2014 Status: Reviewed - No Action Required Author: Roberts, Kris

Updated Volume:

Notes:

Release was into double-lined containment diking and immediately cleaned up. No on-site followup is necessary on this incident.